

# AST 5203ZZ angular contact ball bearings

Our highly-skilled 713618110 Designation FAG and factory-trained service experts have the VKBA 527 Designation SKF resources to help you with all your AST 5203ZZ angular contact ball bearings needs – CX107 Designation SX including routine maintenance, major repairs, warranty service, and equipment inspections.

Designation SKF	VKBA 527
Designation FAG	713618110
Designation SX	CX107
Designation Ruville	6902
Compatibility	TOYOTA / CARINA / engine 1.8 (RA60) / 1981-1985 / front / 2 pcs.TOYOTA / CARINA / engine 1.8 (RA