

Timken 3877A/3820 tapered roller bearings

We 2.0625 in D work closely with our 1.8125 in d Timken 3877A/3820 tapered roller bearings manufacturing partners to No Lubrication Hole lubrication hole type: bring the best value to customers.

d	1.8125 in
lubrication hole type:	No Lubrication Hole
D	2.0625 in
compatible bearing:	BH-3312, BH-3316, MH-33161
width:	1.0150 in
closure type:	N/A
material:	Chrome Steel
type of needle bearing:	Separable Inner Ring Only – Drawn Cup Bearings
series:	IR
manufacturer product page:	Click here
minimum radius:	0.0600 in